

## **SERVICE PARTS LIST**

## **BULLETIN NO.** 54-07-3510

DATE SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS REVISED BULLETIN Jan. 2022 REDLITHIUM® USB 3 Point Laser WIRING INSTRUCTION STARTING 3510-20 CATALOG NO. L39A SERIAL NO

Service needs pertaining to accuracy or calibration can only be performed at Milwaukee Authorized Repair Centers: MILWAUKEE ELECTRIC TOOL central repair 1401 Sycamore Ave. Greenwood, MS 38930-7277 OR Via e-Service at: www.milwaukeetool.com/e-service. Questions,

please call 1.800.SAWDUST

Return it to a MILWAUKEE FACTORY SERVICE CENTER location, freight prepaid and insured. A copy of the proof of purchase should be included with the return product."






FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.	FIG.	NOTES
1	42-92-0118	Battery Cap	(1)	5	A clean, dry surface is essential for proper performance for any
2	42-55-0205	BMC	(1)		adhesive system. The area intended for application of any adhesive
3	48-11-2131	REDLITHIUM® USB 3.0AH Battery (Optional	al) (1)		label or nameplate must be prepared by cleaning with isopropyl
4	48-59-1202	Wall Plug and 3 ft. USB Cable (Optional	ıl) (1)		alcohol. The solvent is to be applied with a clean, lint free applicator
5	12-20-3510	Service Nameplate (Not Shown)	(1)		and the surface allowed to dry before applying the label or name